

●SIZE

12/0  
(外径約2.0mm)

●COLORS

CR2C		CR45		CR107		CR145	
CR5		CR46		CR108			
CR5B		CR47		CR108BD		CR194 (981)	
CR6		CR48		CR109		CR353	
CR6C		CR49		CR109B		CR355	
CR10		CR50		CR110		CR356	
CR19		CR55		CR111		CR400	
CR423 (941)				CR113		CR932	
CR939		CR81		CR114		CR953	
CR942		CR82		CR115		CR959	
CR2151		CR83		CR119		CR960	
CR2152		CR84					
CR2153		CR85		CR121		CR161	
CR2154		CR86		CR122		CR162	
CR2155		CR87		CR123		CR162C	
CR2156						CR163	
		CR101		CR141		CR164	
CR41		CR103		CR142		CR166	
CR42		CR104		CR143		CR166C	
CR43		CR105		CR144		CR167	

●marked colors...These colors may be changed by bleach or oxidation after a while.

★marked colors...These colors may be come off by strong friction.

▲marked colors...These colors may be come off by sunlight(UVs).

CR167BD		CR785		CR329		●★ CR601	
CR168		▲ CR794		CR331		●★ CR602	
▲ CR171D		CR798		CR332		●★▲ CR604	
CR177		CR952		CR421		●★▲ CR605	
CR180				CR425		●★▲ CR607	
		●★ CR221		CR455		●★ CR711	
CR406		●★ CR222		CR457		●★ CR713	
				CR461		●★ CR714	
CR241		CR262				●★ CR721	
CR244		CR264		CR502			
CR252		CR266		CR508		● CR701	
CR303		▲ CR267		CR509		●★ CR712	
CR388		CR271				●★ CR715	
CR539		CR281		●★ CR513			
CR540		CR284		●★ CR514		●★ CR722	
CR770		▲ CR285		●★ CR515			
CR771		▲ CR290		●★ CR562			
CR776		CR294		●★▲ CR563			
CR777				●★▲ CR564			
▲ CR780				●★▲ CR565			

●印のカラー…サラシ(漂白)による変色、あるいは長時間たつと、酸化現象によって変色することがあります。

★印のカラー…強い摩擦によって色落ちすることがあります。

▲印のカラー…太陽光線(紫外線)によって色落ち(褪色)することがあります。



## ●SIZE

15/0  
(外径約1.6mm)

## ●COLORS

CRS2		CRS107		CRS167		CRS290	
CRS5		CRS108		CRS167BD		CRS294	
CRS6		CRS108BD		CRS168			
CRS6C		CRS109		CRS169		CRS321	
CRS7		CRS110		CRS175		CRS329	
CRS7BD		CRS113		CRS176B		CRS332	
CRS9B		CRS114		CRS177		CRS421	
CRS423 (941)		CRS115		CRS178		CRS455	
CRS939		CRS117		CRS179		CRS457	
CRS940		CRS118		CRS180		CRS460	
CRS942		CRS119					
				CRS405		CRS502	
CRS41		CRS121		CRS406		CRS508	
CRS45		CRS122		CRS412			
CRS46		CRS123					
CRS49		CRS127		CRS205		●★ CRS513	
CRS52		CRS132		CRS206		●★ CRS551	
CRS55		CRS133				●★ CRS557	
						●★ CRS565	
CRS81		CRS141		●★ CRS221		●★ CRS571	
CRS82		CRS150		●★ CRS222		●★ CRS602	
CRS83		CRS151				●★▲ CRS605	
CRS84		CRS906		CRS262		●★ CRS711	
CRS85		CRS917		CRS263		●★ CRS713	
CRS90		CRS920		CRS266		●★ CRS721	
				▲ CRS267			
CRS101		CRS161		CRS274		●★ CRS712	
CRS102		CRS162		▲ CRS279			
CRS103		CRS163		CRS281		● CRS740	
CRS106		CRS166C		CRS284			
				▲ CRS285			

●印のカラー…サラシ(漂白)による変色、あるいは長時間たつと、酸化現象によって変色することがあります。

★印のカラー…強い摩擦によって色落ちすることがあります。

▲印のカラー…太陽光線(紫外線)によって色落ち(褪色)することがあります。

●marked colors…These colors may be changed by bleach or oxidation after a while.

★marked colors…These colors may be come off by strong friction.

▲marked colors…These colors may be come off by sunlight(UVs).



●SIZE

9/0  
(diameter:approx. 2.6mm)

●COLORS

CRM5B	
CRM5C	
CRM5D	
CRM49	
CRM55	

CRM81	
CRM82	
CRM83	
CRM84	
CRM85	
CRM86	

CRM121	
CRM122	
CRM123	
★ CRM221	
★ CRM222	

★ CRM565	
★ CRM602	
★ CRM711	
★ CRM713	
★ CRM712	
★ CRM715	

●SIZE

8/0  
(diameter:approx. 3.0mm)

●COLORS

CRL5B	
CRL5C	
CRL5D	
CRL49	
CRL55	

CRL81	
CRL82	
CRL83	
CRL84	
CRL85	
CRL86	

CRL121	
CRL122	
CRL123	
★ CRL221	
★ CRL222	

★ CRL565	

●marked colors...These colors may be changed by bleach or oxidation after a while.

★marked colors...These colors may be come off by strong friction.

※For the color of 5B to 5D, since it is difficult to control of color, it may change the shade of a color for every production.